## MAINTENANCE OF STAIRMASTER OR FLEXMASTER SAFETY RENOVATION TREADS

- 1. Treads should be swept with a broom or vacuumed with a heavy-duty commercial vacuum cleaner at least once a week.
- 2. Treads should be periodically scrubbed with a stiff bristled brush using any commercial or industrial all-purpose cleaner and thoroughly rinsed with clean water after cleaning. We suggest the use of Murphy's Oil Soap<sub>®</sub>. The use of a sponge mop will facilitate the ability to pickup excess water. We recommend two types of brushes, A stiff polypropylene hand brush or use of a stiff polypropylene drill chuck brush that can be installed into a battery operated drill (powered drill brush). The use of these brushes will help speed up the cleaning process and sufficiently scrub the Flextred surface by lifting the accumulated dirt from between the gritted surface. Rinsing with clean water and using the sponge mop to remove excess water will help to eliminate the dirty film if final rinsing was done with dirty water. Note: The drill brush accessory can be found easily by reviewing Industrial Products Catalogs or Call Wooster Products Inc for further details.
- 3. Scuff and heel marks on the aluminum nose can be removed by rubbing with a fine steel wool and a commercial cleaning agent.
- 4. To remove heavy grease and oil from the surface of the treads, use Murphy's Oil Soap and brush vigorously with stiff bristled brush. Rinse with clean water and sponge mop excess mop from the tread surface. Let air dry.
- 5. To remove snow and ice use so dium chloride salt.

## REMOVAL OF CHEWING GUM FROM ABRASIVE SURFACE OF THE TREADS

TOOLS REQUIRED: Putty knife, stiff bristled brush or powered drill brush, clean rags, commercial cleaning agent <u>capable</u> of removing gum, water and a sponge mop.

CLEANING PROCEDURE: Scrape off as much excess chewing gum as possible with a putty knife. If the gum is difficult to scrape off, soak with commercial cleaning agent. This will soften the gum to allow you to remove the excess. It may be necessary to repeat this procedure several times. Vigorously scrubbing with a stiff brush or powered brush as mentioned above will help the cleaning process. Finish the job by cleaning the tread with Murphy's oil soap, stiff brush, clean water, and a sponge mop to remove excess liquid from the tread surface.

## IMPORTANT NOTICE TO PURCHASER: THE FOLLOWING IS MADE IN LIEU OF ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE:

Purchase or use of this product constitutes an agreement with seller and Manufacturer that, if the product proves to be defective or in any way unsuitable, seller's and Manufacturer's limit of liability for all damages, including but not limited to incidental or consequential damages, and User's or Purchaser's exclusive remedy, regardless of legal theory, including theories of breach of warranty, negligence and strict liability, shall be to receive, at Seller's or manufacturer's option, repair of the defective product, an equivalent quantity of replacement product or a refund of the purchase price.